Manitoulin Island Soil Summary Sheet

					POTENTIAL FOR	
Мар	Soil Series and Surface Texture	Natural	Hydrologic	Erosion	Wind	Soil
Symbol		Drainage	Group	Factor	Erosion	Compaction
Basc	Bass Clay	IMPERFECT	VERY SLOW	3	4	Н
Basc-st	Bass Clay - Stony Phase	IMPERFECT	VERY SLOW	3	4	Н
Bis	Bridgman Sand	WELL	RAPID	4	1	L
Bul	Burford Loam	WELL	RAPID	4	2	L
Bul-sh	Burford Loam - Shallow Phase	WELL	RAPID	1	4	L
Bur	Burpee Muck	POOR	SLOW	3	2	M
Buzsc	Buzwah Silty Clay Loam	WELL	SLOW	2	4	M
Busl	Burford Sandy Loam	WELL	RAPID	4	1	L
Buzsc-st	Buzwah Silty Clay Loam - Stony Phase	WELL	SLOW	2	4	M
Buzc	Buzwah Clay Loam	WELL	SLOW	2	4	M
Buzc-sh	Buzwah Clay Loam - Shallow Phase	WELL	SLOW	1	4	M
Bxl	Brisbane Loam	IMPERFECT	MODERATE	2	3	M
Bzfs	Bucke Fine Sandy Loam	WELL	MODERATE	2	4	L
Bzs	Bucke Sandy Loam	WELL	MODERATE	4	2	L
Camc	Campbell Silty Clay Loam	WELL	SLOW	2	4	M
Camc-sh	Campbell Silty Clay Loam - Shallow Phase	WELL	SLOW	1	4	M
Camc-sh-st	: Campbell Silty Clay Loam - Shallow - Stony Phase	WELL	SLOW	1	4	M
Camc-st	Campbell Silty Clay Loam - Stony Phase	WELL	SLOW	2	4	M
Cns	Cane Silt Loam	POOR	VERY SLOW	2	3	Н
Cns-sh	Cane Silt Loam - Shallow Phase	POOR	VERY SLOW	3	3	Н
Cns-st	Cane Silt Loam - Stony Phase	POOR	VERY SLOW	2	3	Н
Cys	Casey Silt Loam	IMPERFECT	MODERATE	3	4	M
Dbs	Donnybrook Sandy Loam	WELL	RAPID	4	1	L
DI	Dumfries Loam	WELL	RAPID	4	2	L
Eas	Earlton Silt Loam	IMPERFECT	MODERATE	2	3	M
Eas-sh	Earlton Silt Loam - Shallow Phase	IMPERFECT	MODERATE	2	4	M
Eas-st	Earlton Silt Loam - Stony Phase	IMPERFECT	MODERATE	2	3	M
Enfs	Englehart Fine Sandy Loam	POOR	SLOW	3	3	Н
Ens	Englehart Sandy Loam	POOR	SLOW	4	3	M
Evs	Evanturel Silt Loam	WELL	MODERATE	1	3	L
Evs-sh	Evanturel Silt Loam - Shallow Phase	WELL	MODERATE	1	4	L
Evs-st	Evanturel Silt Loam - Stony Phase	WELL	MODERATE	1	3	L
FI	Farmington Loam	WELL	MODERATE	1	4	L
Gil	Gilford Loam	POOR	SLOW	3	3	Н
Gis	Gilford Sandy Loam	POOR	SLOW	4	2	M
Gnc	Gordon Silty Clay Loam	IMPERFECT	VERY SLOW	3	4	Н
Gnc-sh	Gordon Silty Clay Loam - Shallow Phase	IMPERFECT	VERY SLOW	3	4	Н
Gnc-sh-st	Gordon Silty Clay Loam - Shallow - Stony Phase	IMPERFECT	VERY SLOW	3	4	Н
Gnc-st	Gordon Silty Clay Loam - Stony Phase	IMPERFECT	VERY SLOW	3	4	Н

Map	Soil Series and Surface Texture	Natural	Hydrologic	Erosion	Wind	Soil
Symbol	Handard Lagra	Drainage	Group	Factor	Erosion	Compaction
Hxl Hxl-sh	Howland Loam Howland Loam - Shallow Phase	IMPERFECT		2 2	3 4	M M
		IMPERFECT	MODERATE	3		
Hxsl	Howland Sandy Loam	WELL	MODERATE	ა 1	2 4	M
Kas Knl	Kagawong Silt Loam Killean Loam		MODERATE	2	3	L M
Ksl		POOR	SLOW	4	2	M
LCc	Kenabeek Sandy Loam Little Current Clay	WELL	MODERATE	2	4	M
Lhc	Leech Clay Loam		VERY SLOW	3	3	H
Lhc-sh	Leech Clay Loam - Shallow Phase		VERY SLOW	3	4	H
Lhsc	Leech Silty Clay Loam		VERY SLOW	3	3	H
Lhsc-sh	Leech Silty Clay Loam - Shallow Phase		VERY SLOW	3	4	H
Lhsc-st	Leech Silty Clay Loam - Stony Phase		VERY SLOW	3	3	 H
Liist-st Li	Lyons Loam	POOR	SLOW	2	3	H
LI-sh	Lyons Loam - Shallow Phase	POOR	SLOW	3	3	H
Lyl	Lily Loam	POOR	SLOW	3	3	H
M	Muck	VERY POOR		3	2	M
Ma	Marsh	VERY POOR		-	-	-
Mal	Mallard Sandy Loam		MODERATE	4	2	M
Mal-sh	Mallard Sandy Loam - Shallow Phase		MODERATE	3	2	M
Mal-st	Mallard Sandy Loam - Stony Phase		MODERATE	4	2	M
Otfs	Otterskin Fine Sandy Loam	IMPERFECT		3	4	M
Ots	Otterskin Sandy Loam	IMPERFECT		3	2	M
Phc	Phipps Clay Loam	POOR	VERY SLOW	3	3	H
Phc-sh	Phipps Clay Loam - Shallow Phase	POOR	VERY SLOW	3	4	H
Phsc	Phipps Silty Clay Loam	POOR	VERY SLOW	3	3	H
Phsc-st	Phipps Silty Clay Loam - Stony Phase	POOR	VERY SLOW	3	3	Н
Pkc	Pike Clay	WELL	SLOW	3	3	M
Pkc-st	Pike Clay - Stony Phase	WELL	SLOW	3	3	M
Prc	Perch Clay	POOR	VERY SLOW	3	3	Н
Prc-st	Perch Clay - Stony Phase	POOR	VERY SLOW	3	3	Н
R	Rock	-	-	-	_	_
Ths	Thwaites Silt Loam	WELL	MODERATE	2	4	L
Val	Vasey Loam	WELL	MODERATE	1	3	L
Val-sh	Vasey Loam - Shallow Phase	WELL	MODERATE	1	4	L
Wdfs	Wendigo Fine Sandy Loam	WELL	RAPID	4	2	L
Wdl	Wendigo Sandy Loam	WELL	RAPID	4	1	L
Wds	Wendigo Sand	WELL	RAPID	4	1	L
Wyc	Wolsey Silty Clay Loam	POOR	VERY SLOW	3	4	Н
Wyc-sh	Wolsey Silty Clay Loam - Shallow Phase	POOR	VERY SLOW	3	4	Н
Wyc-sh-st	Wolsey Silty Clay Loam - Shallow - Stony Phase	POOR	VERY SLOW	3	4	Н
Wyc-st	Wolsey Silty Clay Loam - Stony Phase	POOR	VERY SLOW	3	4	Н